



2013 Mazda Premacy 20S SKYACTIVE

Page 1 of 1

AA Motoring Vehicle Appraisal
2013 MAZDA Premacy Reg: 162363

This appraisal has been prepared by the New Zealand Automobile Association acting as a technical consultant for the Motor Vehicle Dealer named below and not for any prospective purchaser of the vehicle and as such is performed "In Trust" under the Consumer Guarantees Act. The Appraiser to whom this report refers is exempt and holds out of and of responsibility does not include effects or opinions of mental impairments that may be discovered by subsequent monitoring. This report applies to the condition of the vehicle at the time of appraisal.

Purchasers could obtain greater protection from a full AA Vehicle Inspection

Vehicle Inspection Centre: Tauranga AA Inspection Centre
 This report has been carried out for: CAR CONNEXIONS 20907957-3

Inspection Date: 18 Apr 2024 Reg Expiry: WOF: VIN: ZAT0C133X24102460
 Expiry Date: 18 Jun 2024 WOF: Origin: Import
 Odometer: 62224 RUC Expiry: Year First Reg:

Items Covered By This Inspection As Applicable

Brake System Visual External Only	Interior
1 Brakes - Under Body	16 Tires and Accessories
2 Cooling System	17 Road Test
3 Radiator	18 Engine Test
4 Water Pump (where visible)	19 Transmission Test
5 Electric Accessories (Lamps)	20 Exhaust Test
6 Lamps	21 Steering Test
7 Electrical	22 Fuel Brake Test
8 Horn	23 Handbrake Test
9 Battery	24 Air Conditioning
10 Engine Ancillaries	25 Suspension
11 Lubricants (Eng/Trans)	26 Wheels
12 Fuel System	27 Hubs
13 Air Filter	28 Tyres
14 Engine Auxiliary Matters	29 Underbody
15 Engine Noise	30 CV Joints
16 Exhaust System	31 Steering - Under Body
17 Rear View Mirror	32 Transmission
18 Windscreen Wiper	33 Driveshaft
19 Windscreen Washer	34 Axle
20 Airbag Items	35 Differential
21 Fuel System	36 Engine
22 Fuel Filter	37 Exhaust

Tyre Condition

6.0 mm	6.0 mm
7.0 mm	7.0 mm
N/A	Spare

Legal Minimum 1.5mm for Standard Tyres, 4mm for Snow Tyres

12v ELECTRICAL SYSTEM TEST

Battery Test	Starter Test	Charging Test
Good	Good	Good

Good test results, no action required.

Defects Found During Inspection

General Condition

Sound - Vehicle is in above average condition for age and mileage

THIS REPORT IS VALID FOR TWO MONTHS FROM THE DATE OF APPRAISAL OR SHOW WHICHEVER OCCURS FIRST

Page 1 of 1 Inspection Report No: 20907957-3 Version 5.2



VEHICLE INFORMATION

Cash Price
 Includes GST, Registration & Licensing

\$12,990

Finance this vehicle from only

\$87.71 per week*

Total Amount Payable **\$18,244.62**

FINANCE CENTRAL
 powered by Thorn Finance

Body
 5 door, People Movers

Odometer
 62,224 km

Engine
 1997 cc

Fuel Type
 Petrol

Transmission
 Auto, Front Wheel

Reg No.
 -

Ext Colour
 Black

History
 Ex-Overseas

Seats
 7 seats, Cloth

Interior
 Grey, Cloth

Exterior Features

- » Body Kit (Factory)
- » Driving lights
- » Electric doors
- » Electric Mirrors
- » Face Lift Model
- » Keyless entry
- » Rear Wiper
- » Side Skirts
- » Spoiler

Interior Features

- » 6 Airbags
- » Air Conditioning
- » Central Locking
- » Child seat anchor points
- » Climate Control
- » Electric Mirrors
- » Electric Windows
- » Keyless start
- » Multi Airbags

Mechanical Features

- » AA Appraised
- » ABS Braking
- » Auto stop
- » i-Stop
- » Keyless start
- » SKYACTIVE
- » Stability Control



Over 25 years servicing Tauranga and the Bay of Plenty, and 20,000+ quality cars sold nationwide.

Car Connexion, Phone 07 571 1335, Email sales@ccx.co.nz
 141 Second Avenue, Tauranga 3110, New Zealand
 www.ccx.co.nz

* Finance calculation based on a 48 month term, no deposit and with an example annual fixed interest rate of 14.75%. Actual interest rate may be higher or lower. Includes an establishment fee of \$423.00 and a monthly maintenance fee of \$8.50. Full term total amount payable of \$18,244.62. Estimate only, not an offer of finance. Terms, conditions and lending criteria apply.